STATUTORY RULES OF NORTHERN IRELAND

2020 No. 39

ROADS

ROAD TRAFFIC AND VEHICLES

The Motorways Traffic (Amendment) Regulations (Northern Ireland) 2020

Made--19th March 2020Coming into operation29th April 2020

The Department for Infrastructure(1) makes the following Regulations in exercise of the powers conferred by Article 20(3) of the Roads (Northern Ireland) order 1993(2) and now vested in it(3).

Citation and commencement

1. These Regulations may be cited as The Motorways Traffic (Amendment) Regulations (Northern Ireland) 2020 and shall come into operation on 29th April 2020.

Amendment

2. The Motorways Traffic Regulations (Northern Ireland) 2008(4) are amended by the substitution for Schedule 1 of the Schedule set out in the Schedule to these Regulations.

Sealed with the Official Seal of the Department for Infrastructure on 19th March 2020

(L.S.)

Elizabeth Loughran A senior officer of the Department for Infrastructure

^{(1) 2016} c. 5 (N.I.)

⁽²⁾ S.I. 1993/3160 (N.I. 15)

⁽³⁾ S.R. 1999 No. 481 Article 6(d) and Schedule 4 Part IV

⁽⁴⁾ S.R. 2008 No. 135 as amended by S.R. 2019 No. 19

Status: This is the original version (as it was originally made). This item of legislation is currently only available in its original format.

SCHEDULE

Article 2

Regulations 1(2) and 9(a)

"SCHEDULE 1

and from a point 225 matrice north

1. The area of the hard shoulder of the Motorway M1 eastbound, from a point 325 metres northeast of the north-eastern end of Halftown Road Bridge abutment, to a point 755 metres north-east of the north-eastern end of Halftown Road Bridge abutment, bounded on its north-western side by the north-western edge of the hard shoulder, and on its south-eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

2. The area of the hard shoulder of the Junction 8 eastbound off-slip of the Motorway M1 eastbound, from a point 755 metres north-east of the north-eastern end of Halftown Road Bridge abutment, to a point 200 metres north-east of the north-west end of the gantry spanning the Junction 8 eastbound off-slip bounded on its north-western side by the north-western edge of the hard shoulder, and on its south-eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

3. The area of the hard shoulder of the Junction 8 eastbound on-slip to the Motorway M1 eastbound, from the A101 entry to the on-slip, to a point 137 metres south-west of the centreline of the Junction 7 on-slip road where it passes under the Motorway M1, bounded on its northern side by the kerb at the northern edge of the hard shoulder, and on its southern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

4. The area of the hard shoulder of the Motorway M1 eastbound, from a point 137 metres southwest of the centreline of the Junction 7 on-slip road under the Motorway M1, to a point 133 metres north-east of the centreline of the Junction 7 on-slip road under the Motorway M1, bounded on its north-western side by the north-western edge of the hard shoulder, and on its south-eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

5. The area of the hard shoulder of the Motorway M1 eastbound, from a point 45 metres north-east of the north-eastern end of the northern parapet of Ravernet Road Bridge, to a point 340 metres southwest of the south-western end of the north-eastern parapet of Ballynahinch Road Bridge bounded on its north-western side by the north-western edge of the hard shoulder, and on its south-eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

6. The area of the hard shoulder of the Motorway M1 eastbound, from a point 146 metres northeast of the north-western parapet wall of the Hillhall Road Bridge to a point 215 metres north-east of the north-western parapet wall of the Tullynacross Road Bridge bounded on its western side by the western edge of the hard shoulder and on its eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

7. The area of the hard shoulder of the Motorway M1 eastbound, from a point 590 metres northeast of the north-western parapet wall of the Tullynacross Road Bridge to a point 592 metres southwest of the western parapet wall of the Ballyskeagh Road Bridge bounded on its western side by the western edge of the hard shoulder and on its eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

8. The area of the hard shoulder of the Motorway M1 eastbound, from a point 83 metres southwest of the western parapet wall of the Ballyskeagh Road Bridge to a point 187 metres north-east of the northern parapet of the Black's Road Bridge bounded on its western side by the western edge of the hard shoulder and on its eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

9. The area of the hard shoulder of the Motorway M1 eastbound, from a point 700 metres northeast of the north-eastern end of the north-western parapet wall of Stockman's Lane Bridge, to the junction of that hard shoulder and Donegall Road, bounded on its north-western side by the northwestern edge of the hard shoulder, and on its south-eastern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

10. The area of the hard shoulder of the Motorway M2 southbound, from a point 490 metres north-west of the centre line of Ballycraigy Road South where it passes under the Motorway M2 at Ardkeen Bridge to its junction with the Sandyknowes Roundabout at the end of the southbound off-slip, bounded on its eastern side by the eastern edge of the hard shoulder and on its western side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

11. The area of the hard shoulder of the on-slip from Sandyknowes Roundabout, Newtownabbey, to the Motorway M2 southbound, from a point 29 metres south-east of that hard shoulder's junction with the hard shoulder of Sandyknowes Roundabout, to its junction with the hard shoulder of the Motorway M2 southbound, bounded on its north-eastern side by the north-eastern edge of the hard shoulder, and on its south-western side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

12. The area of the hard shoulder of the Motorway M2 southbound, from its junction with the hard shoulder of the southbound on-slip road from Sandyknowes Roundabout, to a point 54 metres west of the north-eastern end of the western parapet wall of Hightown Bridge, bounded on its northern side by the northern edge of the hard shoulder, and on its southern side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

13. The area of the hard shoulder of the Motorway M2 southbound, from a point 430 metres south-west of the south-eastern end of the eastern parapet of the M5 Over Bridge, to the end of the hard shoulder of the southbound off-slip at its junction with the Fortwilliam Roundabout bounded on its eastern side by the eastern edge of the hard shoulder and on its western side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

14. The area of the hard shoulder of the on-slip road from Fortwilliam Roundabout to the Motorway M2 southbound, from a point 260 metres south-east of that hard shoulder's junction with the hard shoulder of Fortwilliam Roundabout, to its junction with the hard shoulder of the Motorway M2 southbound, bounded on its eastern side by the eastern edge of the hard shoulder, and on its western side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons.

15. The area of the hard shoulder of the Motorway M2 southbound, from its junction with the hard shoulder of the on-slip road from Fortwilliam Roundabout, to a point 244 metres south of the centre line of Milewater Footbridge bounded on its eastern side by the eastern edge of the hard shoulder and on its western side by the outer edge of a road marking in the form of—

- (a) a broken longitudinal white line; or
- (b) two continuous longitudinal white lines encompassing white chevrons."

EXPLANATORY NOTE

(This note is not part of the Order)

This Order amends The Motorways Traffic Regulations (Northern Ireland) 2008 ("the Regulations") by the substitution for Schedule 1 of the Schedule specified in the Schedule to these Regulations adding lengths of bus lane on the hard shoulder of the M1 Motorway at Sprucefield.

Any person who acts in contravention of the Regulations shall be guilty of an offence and shall be liable on summary conviction to a fine not exceeding level 4 on the standard scale (£2500). Traffic signs indicating the effect of the Regulations will in due course be placed on the road.